Citroën / Lancia / Fiat / Peugeot

VKMA 03264

VKMA 03266





VKMC 03264

VKMC 03266






(4): Flywheel locking tool (ref. 0188F).


Α

- (5): Flywheel timing pin (ref. 0188X).
- (6): Camshaft timing pin (ref. 0188M).
- (9): Belt fitting tool (ref. 0188K).
- (11): Belt tension adjustment tool (ref. 0188J2).
- (10) SEEM tension gauge (CTG 105.5M) (ref. 0192).
- (17): Crankshaft pulley puller (ref. 0188P).






- (7): 23 Nm(engines DW-12TED4) / 25 Nm (engines DW12TED)
- (8): 20 Nm (14): 15 Nm
- (15): 43 Nm
- (16): 40 Nm + 51° (DW12T-ED4) or 50 Nm + 62° (DW12TED)





- Disconnect the battery according to the vehicle manufacturing guidelines.
- Prepare the vehicle for the timing replacement according to the vehicle manufacturing quidelines.
- 3) Lock the flywheel using tool (4) (Fig. B).
- 4) Remove the crankshaft pulley using the puller (17) (Ref. 0188P).
- 5) Remove the tool (4) (Fig. B).
- 6) Turn the crankshaft in the engine rotation direction until the timing pin (5) can be inserted in the flywheel (Fig. C).
- 7) Insert pin (6) in the camshaft hub (Fig. D).
- 8) Loosen the tensioner roller (2) fastening bolt (7) (Fig. D).
- Remove timing belt (1), tensioner roller (2) and idler roller (3) (Fig. D).
- 10) Removing the water pump (VKMC 03264/03266): Firstly bleed the cooling circuit, check it is clean, and clean if required; secondly fully loosen the water pump fastening bolts (14) and remove the pump (13) (Fig. A).




## Refitting


**Caution!** First clean the bearing surfaces of the rollers.


- 11) Refitting the water pump: Firstly fit the new water pump (13), apply the torque 15 Nm to the waterpump bolts (14); then check that the water pump pulley runs properly, and has no hard or locking spots.
- 12) Fit the new tensioner roller (2).
- **13)** Fit the new idler roller (3) and tighten its fastening bolt (**15**) to **43 Nm**.
- 14) Loosen the camshaft sprocket fastening bolts (8) (Fig. D).
- **15)** Retighten by hand the camshaft sprocket fastening bolts **(8)** (**Fig. D**).
- 16) Move the camshaft sprocket to the end of the oblong holes by turning it in the engine rotation direction.
- **17)** Place the new timing belt (**1**) on the crankshaft sprocket and immobilize with tool (**9**) (**Fig. E**).

## **Install Confidence**









**18)** Continue fitting the timing belt **(1)** in the following order: idler roller **(3)**, high pressure pump sprocket, camshaft sprocket, water pump sprocket and tensioner roller **(2)**.

**Note:** To help place the belt on the camshaft and high pressure pump sprockets, turn the camshaft sprocket very slightly in an **anti-clockwise** direction. The angular displacement of the camshaft sprockets relative to the belt must not exceed one tooth.

- 19) Remove the tool (9) (Fig. E).
- 20) Place the sensor (10) of the tension gauge on the belt (1) between the the camshaft and high pressure pump sprockets (Fig. D).
- 21) Tighten the timing belt: insert the tool (11) (Fig. F) in the hole (12) and turn the tensioner roller (2) anti-clockwise until a reading of 98 SEEM units is displayed on the tension gauge (Fig. D).
- 22) Tighten the fastening bolt (7) of the tensioner roller (2) to 23 Nm (engines DW12TED4) or 25 Nm (engines DW12TED).
- 23) Check that the camshaft sprocket is not bearing against the end of the oblong holes. Tighten the camshaft sprocket fastening bolts (8) to 20 Nm (Fig. D).
- 24) Remove the sensor (10) (Fig. D).
- 25) Remove the timing pins (5), and (6) (Fig. C and Fig. D).

- 26) Turn the crankshaft through 8 revolutions in the engine rotation direction until pins (5) and (6) can be inserted (Fig. C and Fig. D).
- Loosen the camshaft sprocket fastening bolts
  (8) as well as those of the tensioner roller (2)
  (Fig. D).
- 28) Place the sensor (10) on the belt (1) (Fig. D).
- 29) Insert the tool (11) (Fig. F) in the hole (12) and turn the tensioner roller (2) until a reading of 51 ± 2 SEEM units (engines DW12TED4) or 54 ± 2 SEEM units (engines DW12TED) is displayed on the tension gauge (Fig. D).
- 30) Tighten the fastening bolt (7) of the tensioner roller (2) to 23 Nm (DW12TED4 engines) or 25 Nm (DW12TED engines). Tighten the camshaft sprocket fastening bolts (8) to 20 Nm (Fig. D).
- 31) Remove then refit the sensor (10) and check that the tension reading is between 48 and 55 SEEM units (engines DW12TED4) or equal to 54 ± 3 SEEM units (engines DW12TED) (Fig. D).
- 32) If the tension is not correct, loosen the camshaft sprocket fastening bolts (8) and the tensioner roller fastening bolt (7), refit the pin (5) and (6) and re-start the tension adjustment operation from step 21.
- 33) Remove the sensor (10) (Fig. D).

- 34) Remove the timing pins (5), and (6) (Fig. C and Fig. D).
- 35) Turn the crankshaft through 2 revolutions in the engine rotation direction until pin (5) can be inserted (Fig. C).
- 36) Remove the timing pin (5).
- 37) Refit the removed elements in reverse order to removal:
  - Lock the flywheel using tool (4) (Fig. B).
  - Refit the crankshaft pulley and tighten its new bolt (16) (VKMA/C 03264) (Fig. A) to 40 Nm + 51° (DW12TED4) or 50 Nm + 62° (DW12TED)
  - Remove the tool (4) (Fig. B).
- **38)** Fill the cooling circuit with the permanent fluid recommended.
- 39) Check the circuit's leak-tightness when the engine reaches its running temperature and secure the level of coolant when the engine is at ambient temperature (20 °C).

Notice: Always follow the vehicle manufacturer instructions when working on the engine. The SKF KITS are designed for the automotive repair professional and must be fitted using tooling used by these professionals. These instructions are to be used as a guideline only. This document is the exclusive property of SKF. Any representation, partial or full reproduction, is forbidden without prior written consent from SKF.



© SKF Group 2014

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless prior written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use of the information contained herein. Any cost savings and revenue increases in this publication are based on results experienced by SKF customers and do not constitute a guarantee that any future results will be the same.

