

to fit:  
Mercedes Benz Sprinter,  
Vito, Viano and VW Crafter, LT

EN

## Efficient repair solution for Mercedes Benz Sprinter, Vito, Viano and VW Crafter, LT!

Initial warning signs that indicate trouble and faults in the area of the propshaft:

- Noises coming from the direction of the vehicle's underbody, mostly at specific revs/speeds
- Unusual vibrations
- Knocking noises in gear change situations

The reason for this may be a faulty or worn universal joint. This may result in complete failure of the power train. Always replace the joint if in doubt.

### Note!

The universal joint is not available separately in the OE segment. This means replacement of the complete propshaft with high costs for the vehicle owner.

**At febi we have a reasonably priced and technically perfect repair solution for you and your customer.**



febi	a, mm	b, mm
14512	74.5	24
38414	88	31
38415	75	27
38416	88	24
38417	88	27

### You only replace the universal joints.

Your customer is bound to be pleased with the lower cost.

### Attention:

Often in online parts identification tools, several universal joints are assigned to a vehicle type. Before ordering parts we recommend matching the dimensions of the old universal joint. To do this, please measure the length of the universal joint with lightly pressed-on bearings (a) and also the outside diameter of one of the four caps (b).

For more technical information please visit: [partsfinder.bilsteingroup.com](http://partsfinder.bilsteingroup.com)