

SKF Product Information

Driveshaft design improvements



Passenger cars and Light Commercial Vehicles



SKF Driveshaft design improvements



SKF Driveshaft design changes

For the above applications, SKF has upgraded the driveshaft design. The new driveshaft design, made in Italy, is in line with OE specifications and complies with OE product quality and performance. The boot material of the CV-Joint (Wheel side) is Thermoplastic as per OE material.

The former SKF design also guarantees optimal fitting and performance.




Former SKF design



New SKF design



The SKF CV-Joint always matches with the new SKF Driveshaft design, as per the table of applications on the following page. For a professional repair, an SKF driveshaft fitted on a vehicle always need a new SKF CV-Joint!



SKF Product Information

Driveshaft design improvements

Below is the list of affected kits with the Driveshaft design change and the corresponding CV-Joint to mount in case of CV-Joint damage.

Car Make	OE Nb Driveshaft kit	SKF Driveshaft kit	SKF CV-Joint kit
VAG Ford	7M3 407 761 YM21-3B437-AC	VKJC 7004	VKJA 3002
VAG	1K0 407 271 EE	VKJC 4592	VKJA 3945
PSA Fiat	3273.NP 71792561	VKJC 8525	VKJA 3028
Mercedes	A 169 370 55 72	VKJC 3305	VKJA 5356
Renault	77 11 135 005	VKJC 8102	VKJA 5354
PSA	3272.NP	VKJC 8523	VKJA 3945
VAG	1K0 407 272 EN	VKJC 4620	VKJA 3028
BMW	31 60 7 565 313	VKJC 1209	VKJA 5923
Mercedes	A 169 370 56 72	VKJC 3303	VKJA 5349
PSA Fiat	3273.CK 51872270	VKJC 4508	VKJA 3945
BMW	31 60 7 565 314	VKJC 1210	VKJA 5923
Renault	77 01 469 374	VKJC 1286	VKJA 5354
PSA Fiat	3273.CJ 1495538080	VKJC 4507	VKJA 3945
VAG	8D0 407 272 DL	VKJC 5466	VKJA 5923
VAG	8D0 407 272 EK	VKJC 5480	VKJA 3001
Renault	77 11 135 243	VKJC 1283	VKJA 5354
VAG	8E0 407 271 BE	VKJC 5519	VKJA 3002
Opel	95516047		
Nissan	39101-00Q4F	VKJC 1353	VKJA 3040
Renault	39 10 126 75R		
Renault	77 01 352 882	VKJC 2896	VKJA 5354
Opel	95516046		
Nissan	39100-00Q4H	VKJC 1352	VKJA 3040
Renault	39 10 051 87R		
VAG	8D0 407 272 BB	VKJC 4879	VKJA 3002
VAG	8D0 407 271 BB	VKJC 5444	VKJA 3002
Renault	82 00 844 451	VKJC 1296	VKJA 5354
Fiat	51872270	VKJC 3676	VKJA 3945



An SKF driveshaft fitted on a vehicle always need a new SKF CV-Joint!

[Click here to watch SKF technical videos on Youtube!](#)